


Identification Guide

hatchbag.us


Land Rover Discovery Sport - 2015-present

Our ref: H0597

Question 1 - Vehicle Identification Guide



When the seats are most upright there is a void between the seat upper and the plastic molding



When the seats are most reclined there is no void between the seat upper and the plastic molding

The Rear Seats must be slid as far BACK to the lift gate

The rear seats (2nd-row) slide – the cargo liner only suits these seats slid as far back to the liftgate

Next page





/!



Identification Guide

hatchbag.us



RCSNO AVAILABLE

No recess in cargo area sides

Right side has plastic vent panel OR net (cargo liner skims over net)

