

Ford EcoSport - 2018 - present

Our ref: H0755

Question 1 - Vehicle Identification Guide

SH1



AVAILABLE

Cargo area shape 1



Left side



Right side

SH2



NOT AVAILABLE

Cargo area shape 2



Left side



Right side



Next page



Question 2 - Vehicle Identification Guide

FOUT



AVAILABLE

False floor removed

The false floor has been removed from the vehicle



FLOW



NOT AVAILABLE

False floor lowered

The false floor is stored at the very lowest position, and not located into the plastic mounting brackets



FMD



AVAILABLE

False floor at mid position

The false floor is located into plastic mounting brackets at the low position



FRSD



NOT AVAILABLE

False floor is in highest position

The false floor is located into plastic mounting brackets at the highest position

