Ford EcoSport - 2018 - 2022

Our ref: H0755

Question 1 - Vehicle Identification Guide

SH1

AVAILABLE

Cargo area shape 1

Left side

Right side

SH2

NOT AVAILABLE

Cargo area shape 2

Left side

Right side

Next page

Question 2 - Vehicle Identification Guide

FOUT

AVAILABLE

False floor removed

The false floor has been removed from the vehicle

FLOW

NOT AVAILABLE

False floor lowered

The false floor is stored at the very lowest position, and not located into the plastic mounting brackets

FMID

AVAILABLE

False floor at mid position

The false floor is located into plastic mounting brackets at the low position

FRSD

NOT AVAILABLE

False floor is in highest position

The false floor is located into plastic mounting brackets at the highest position